

ÖVERSIKT KOPPLINGAR DIN11864

Skruvkoppling DIN 11864-1		Artikelnummer
	Svetshylsa (o-ringsdel / liner / bund) Serie A – DIN 5:27 Serie B – ISO 5:29 Serie C – OD 5:31	6330-
	Svetsnippel (ej o-ringsdel / male part / gewind) Serie A – DIN 5:27 Serie B – ISO 5:29 Serie C – OD 5:31	6350-
	O-ring, aseptisk Serie A – DIN 5:28 Serie B – ISO 5:30 Serie C – OD 5:32	6370-
	Mutter (nut) DIN 11851 Samma mutter till samtliga standarder 5:28	0360-
Flänskoppling DIN 11864-2		Artikelnummer
	Svetsfläns (o-ringsdel / groove / nut) Serie A – DIN 5:33 Serie B – ISO 5:35 Serie C – OD 5:37	6880-
	Svetsfläns (ej o-ringsdel / collar / bund / liner) Serie A – DIN 5:33 Serie B – ISO 5:35 Serie C – OD 5:37	6881-
	O-ring, aseptisk Serie A – DIN 5:34 Serie B – ISO 5:36 Serie C – OD 5:38	6370-
Clampkoppling DIN 11864-3		Artikelnummer
	Clampsvetshylsa (o-ringsdel / groove / nut) Serie A – DIN 5:39 Serie B – ISO 5:41 Serie C – OD 5:43	6520-
	Clampsvetshylsa (ej o-ringsdel / collar / bund / liner) Serie A – DIN 5:39 Serie B – ISO 5:41 Serie C – OD 5:43	6521-
	O-ring, aseptisk Serie A – DIN 5:40 Serie B – ISO 5:42 Serie C – OD 5:44	6370-
	Clampbygel Samma bygel till samtliga standarder 5:40	0500-